

BUDGET ANALYSIS

Client Information:

Double Hung Insert Window Replacements

Address:

City, State, Zip:

Phone:

Email:

Project Description:

Replace (10) existing 3'x4' double-hung windows with Marvin Signature full frame windows. Insulate weight pocket. Replace existing interior and exterior trim. Interior of window inserts to be stained to match existing interior trim work. Drywall touch up and interior painting included. Haul away all debris.

NOTE: Material and Labor is included for items listed below, unless otherwise noted.							
	Qty. Unit	Image	Low I	Budget	High 1	Budget	
01. Permits and Design							
Permit.	1 EA		\$	840.00	\$	966.00	
<u>Design and Planning Process</u> - see Design and Planning Agreement for details.	1 EA		\$	350.00	\$	350.00	
Subtotal - Category 1			\$	1,190.00	\$	1,316.00	
02. Site Prep and Demolition							

		_			_
Client Responsibilities: -Remove personal items from work areas including food, appliances, furniture, and valuablesRemove valuables, art, and personal items from walking paths to restrooms and entry/exit and the other side of walls adjacent to work area.	1 EA	\$	0.00	\$	0.00
Site Prep Small to Medium Project: -Tools/equipment delivery and set up of job sitePlace yard sign and order dumpsterFloor protection to work areaPoly curtain walls and zipper doors to work area.	1 EA	\$	275.99	\$	317.39
Demolition of work area: - Remove (10) double hung sash sets on main level Remove interior & exterior trim/millwork.	1 EA	\$	1,098.62	\$	1,263.41
NOTE: Although care is taken to carefully complete demolition, screw pops, hairline cracks, and can occasionally arise in adjacent spaces. No costs are included in this estimate to patch drywal repaint walls in adjacent spaces, but the need could arise. We also use the most expensive and s when taping prep to the floor, walls, or trim. If it is a bad or old finish, there is a small chance t off some of the existing finish. Any additional repairs will be an extra charge and dealt with via	ll or plaster or ensitive tape that it may peel	-			
Subtotal - Category 2		\$	1,374.61	\$	1,580.80
03. Landscaping and Fence					
Subtotal - Category 3		\$	-	\$	-
04. Concrete and Foundation					
Subtotal - Category 4		\$	-	\$	-
05. Masonry					
Subtotal - Category 5		\$	-	\$	-
06. Framing					
Subtotal - Category 6		\$	-	\$	-
09. Roofing, Flashing, Gutters					
Subtotal - Category 9		\$	-	\$	-
10. Exterior Trim, Porches and Decks					
Trim- Miratec or paint grade: Width: Thickness: Profile if backband detail: Texture: NOTE: double the LF if backband is needed as well.	200 LF	\$	1,835.02	\$	2,110.27
Subtotal - Category 10		\$	1,835.02	\$	2,110.27
<u> </u>					
11. Siding, Soffit, and Fascia		\$		\$	_
11. Siding, Soffit, and Fascia Subtotal - Category 11		Ф	_		
		3	_	4	

13. Windows						
Furnish and install new clad/	wood full frame window:	10 EA	\$	20,609.35	\$	23,700.7
\$1180 allowance						
Manufacturer: Marvin						
Line: Ultimate						
	npering, egress notes: see plan/schedule					
Exterior material/color:						
Interior material/color:						
	is standard- modify if something else desired					
Grids (type, size, pattern, color	·):					
Weather strip color:						
Hardware type/color:	1 (01)00 0 1 1					
WOCD: Y or N (and specify of						
Screen surround material/color	•					
Screen color:		10 1				
•	aterial/color/size: if comes with window, if not spe	CITY under				
section 10 *for budget analysis	•					
Subtotal - Category 13	A TANBARA MINI		\$	20,609.35	\$	23,700.7
14. Plumbing						
<u>NOTE:</u> During kitchen and be periods of time with no water sometimes can come free and project. There is no money in	bathroom remodels, the pipes (drains and galvan going through them. The build up on the inside clog either a drain or water line, once the water cluded to unclog a pipe if this happens and addit	of the pipes dries up and is turned back on at the end of the ional charges will occur.	S	0.00		
NOTE: During kitchen and be periods of time with no water sometimes can come free and project. There is no money in NOTE: Any new waste or support the project.	going through them. The build up on the inside clog either a drain or water line, once the water	of the pipes dries up and is turned back on at the end of the ional charges will occur.	I c	0.00	· ·	0.0
NOTE: During kitchen and be periods of time with no water sometimes can come free and project. There is no money in NOTE: Any new waste or sufficient of Category 14	going through them. The build up on the inside clog either a drain or water line, once the water cluded to unclog a pipe if this happens and addit	of the pipes dries up and is turned back on at the end of the ional charges will occur.	\$	0.00	\$	0.0
NOTE: During kitchen and be periods of time with no water sometimes can come free and project. There is no money in NOTE: Any new waste or sufficient of Category 14	going through them. The build up on the inside clog either a drain or water line, once the water cluded to unclog a pipe if this happens and addit	of the pipes dries up and is turned back on at the end of the ional charges will occur.				0.0
NOTE: During kitchen and be periods of time with no water sometimes can come free and project. There is no money in NOTE: Any new waste or superiodubtotal - Category 14 15. HVAC Subtotal - Category 15	going through them. The build up on the inside clog either a drain or water line, once the water cluded to unclog a pipe if this happens and addit	of the pipes dries up and is turned back on at the end of the ional charges will occur.	\$	0.00	\$	0.0
<u>NOTE:</u> During kitchen and be periods of time with no water sometimes can come free and project. There is no money in	going through them. The build up on the inside clog either a drain or water line, once the water cluded to unclog a pipe if this happens and addit	of the pipes dries up and is turned back on at the end of the ional charges will occur.				0.0
NOTE: During kitchen and be periods of time with no water sometimes can come free and project. There is no money in NOTE: Any new waste or support of the NOTE: Any new waste or support of the NOTE: Entire home must mee functional and placed per cod needs a smoke detector. There	going through them. The build up on the inside clog either a drain or water line, once the water cluded to unclog a pipe if this happens and addit pply lines will be plastic, not copper or galvanized pely lines will be plastic, not copper or galvanized pely lines will be plastic, not copper or galvanized pely lines will be requirements for smoke and CO detector le. Code requires each floor to have one smoke dee must also be a carbon monoxide detector within the above code, Client will be responsible to up	of the pipes dries up and is turned back on at the end of the tional charges will occur. d. The state of the end of the tector. In addition, any bedroom to 10 feet of each bedroom. If the				0.0
NOTE: During kitchen and be periods of time with no water, sometimes can come free and project. There is no money in NOTE: Any new waste or support of the home waste or support of the home must me functional and placed per code needs a smoke detector. There rest of the home does not mee will perform updates and a check not mee will perform updates and a check not mee.	going through them. The build up on the inside clog either a drain or water line, once the water cluded to unclog a pipe if this happens and addit pply lines will be plastic, not copper or galvanized pely lines will be plastic, not copper or galvanized pely lines will be plastic, not copper or galvanized pely lines will be requirements for smoke and CO detector le. Code requires each floor to have one smoke dee must also be a carbon monoxide detector within the above code, Client will be responsible to up	of the pipes dries up and is turned back on at the end of the isonal charges will occur. d. s. All detectors need to be etector. In addition, any bedroom in 10 feet of each bedroom. If the idate it or if Client prefers, Castle pricing. If any low voltage wires				0.0
NOTE: During kitchen and be periods of time with no water, sometimes can come free and project. There is no money in NOTE: Any new waste or supubtotal - Category 14 15. HVAC Subtotal - Category 15 16. Electrical NOTE: Entire home must me functional and placed per cod needs a smoke detector. There rest of the home does not mee will perform updates and a che NOTE: No wiring for security are found in a wall being open	going through them. The build up on the inside clog either a drain or water line, once the water cluded to unclog a pipe if this happens and addit pply lines will be plastic, not copper or galvanized by lines will be plastic, not copper or galvanized by lines will be plastic, not copper or galvanized by lines will be plastic, not copper or galvanized by lines will be plastic, not copper or galvanized by lines will be requires each floor to have one smoke do a must also be a carbon monoxide detector withing the good of the lines will be responsible to up lange order will be issued. The lines will be issued by lines and lines are lines and lines and lines and lines are lines and lines and lines are lines are lines are lines and lines are lines are lines are lines are lines are lines are lines and lines are	of the pipes dries up and is turned back on at the end of the cional charges will occur. d. d. s. All detectors need to be elector. In addition, any bedroom in 10 feet of each bedroom. If the eldate it or if Client prefers, Castle pricing. If any low voltage wires ur.	\$	0.00	\$	0.0
NOTE: During kitchen and be periods of time with no water, sometimes can come free and project. There is no money in NOTE: Any new waste or supubtotal - Category 14 5. HVAC ubtotal - Category 15 6. Electrical NOTE: Entire home must me functional and placed per cod needs a smoke detector. There rest of the home does not mee will perform updates and a ch	going through them. The build up on the inside clog either a drain or water line, once the water cluded to unclog a pipe if this happens and addit pply lines will be plastic, not copper or galvanized by lines will be plastic, not copper or galvanized by lines will be plastic, not copper or galvanized by lines will be plastic, not copper or galvanized by lines will be plastic, not copper or galvanized by lines will be requires each floor to have one smoke do a must also be a carbon monoxide detector withing the good of the lines will be responsible to up lange order will be issued. The lines will be issued by lines and lines are lines and lines and lines and lines are lines and lines and lines are lines are lines are lines and lines are lines are lines are lines are lines are lines are lines and lines are	of the pipes dries up and is turned back on at the end of the isonal charges will occur. d. s. All detectors need to be etector. In addition, any bedroom in 10 feet of each bedroom. If the idate it or if Client prefers, Castle pricing. If any low voltage wires				0.0

NOTE: For all home client provided fixtures, there may be additional install costs for more complicated fixtures. ALL light fixtures must be specified prior to contract signing and be UL listed to pass inspection. All material issues related to materials supplied by client are the responsibility of the client to resolve. Extra trade partner trip charges may apply for return visits if material issues can not be resolved in timely manner. Subtotal - Category 16 0.00\$ 0.00 17. Insulation NOTE: if insulation is replacing vermiculite insulation, part of the replacement cost may be eligible for reimbursement via the zonolite attic insulation trust. In that case, client can subcontract work directly. This cost is for project manager to coordinate scheduling/misc. with client only. Subtotal - Category 17 0.00 0.00 18. Drywall Subtotal - Category 18 19. Tile and Stone Subtotal - Category 19 20. Millwork, Doors, Hardware 4,054.54 Casing- classic 1X with a backband: 200 LF 3,525.69 Manufacturer: Model backband: Model 1x: Species: Size overall: Picture framed: Y or N Stool detail (thickness/extension) and apron detail (height, model #): or NA Subtotal - Category 20 3,525.69 4,054.54 21. Cabinetry, Countertops and Appliances

CABINET SPECS:	1 EA	\$	0.00	\$	0.00
Cabinet Line: Crystal Current, Keyline, or Encore	1 2.1	•	0.00	Ψ	0.00
Box Type: Framed, Inset, or Frameless					
Door Construction: MDF or Wood					
Door Style:					
Drawer Style: 5 piece or slab					
Drawer box construction:					
Interior material: current- natural melamine on particle board substrate standard or natural					
basswood veneer on plywood substrate upgrade, white melamine on particle board substrate					
available current frameless, all plywood green core box with natural maple veneer available if					
keyline; finished interiors of any cabinets would be noted on plans.					
Wood Species:					
Finish: paint or stain					
Color:					
Sheen:					
Specialties: (distressing, highlights, etc.)					
Crown:					
Shoe: Yes					
Finished end: Furniture groove finished end (standard) or optional upgrade to flush finished					
Any applied doors or end panels to sides or backs of cabinets will be noted on plans. If not on					
drawing, not included.					
Crystal accessories (location noted on plan):					
Other accessories provided by Castle (location noted on plan)::					
Other modifications will be noted on plan- examples: finished bottoms, recessed bottoms.					
Subtotal - Category 21		\$	0.00	\$	0.00
22. Specialties					0.00
22. Specialties Subtotal - Category 22		\$	-	\$	-
22. Specialties					-
22. Specialties Subtotal - Category 22 23. Flooring	isting hardwoods are				- 0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exit.	•				- 0.00
22. Specialties Subtotal - Category 22 23. Flooring	•				-
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exirefinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood.	•	s	0.00	\$	0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exirefinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23	•				0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exirefinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating	•	\$	0.00	\$	0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exirefinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms.	g grains and ages	\$ \$ \$	0.00	\$	0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exirefinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing:	g grains and ages	\$	0.00	\$	0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exirefinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing: Manufacturer:	g grains and ages	\$ \$ \$	0.00	\$	0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exit refinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing: Manufacturer: Color name and #:	g grains and ages	\$ \$ \$	0.00	\$	0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exirefinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing: Manufacturer: Color name and #: Sheen: satin is standard	g grains and ages	\$ \$ \$	0.00	\$	0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exit refinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing: Manufacturer: Color name and #: Sheen: satin is standard Items: base, casing, crown, etc.	g grains and ages	\$ \$ \$	0.00	\$	0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exirefinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing: Manufacturer: Color name and #: Sheen: satin is standard	g grains and ages	\$ \$ \$	0.00	\$	0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exit refinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing: Manufacturer: Color name and #: Sheen: satin is standard Items: base, casing, crown, etc.	g grains and ages	\$ \$ \$	0.00	\$	0.00
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exit refinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing: Manufacturer: Color name and #: Sheen: satin is standard Items: base, casing, crown, etc. Rooms or locations:	1 EA 200 LF	\$ \$ \$ \$ \$ \$	0.00 521.98 2,211.48	\$ \$ \$ \$	0.00 600.27 2,543.21
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exit refinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing: Manufacturer: Color name and #: Sheen: satin is standard Items: base, casing, crown, etc. Rooms or locations: Window- priming and painting on interior side of window:	1 EA 200 LF	\$ \$ \$ \$ \$ \$	0.00 521.98 2,211.48	\$ \$ \$ \$	0.00 600.27 2,543.21
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exit refinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing: Manufacturer: Color name and #: Sheen: satin is standard Items: base, casing, crown, etc. Rooms or locations: Window- priming and painting on interior side of window: Manufacturer:	1 EA 200 LF	\$ \$ \$ \$ \$ \$	0.00 521.98 2,211.48	\$ \$ \$ \$	0.00 600.27 2,543.21
22. Specialties Subtotal - Category 22 23. Flooring NOTE: New and existing hardwood flooring will not match exactly. Even when adjacent exirefinished or stained to achieve a closer match, differences will be apparent due to the varying of the wood. Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up- 3 or more rooms. Molding (base, casing)- staining and sealing: Manufacturer: Color name and #: Sheen: satin is standard Items: base, casing, crown, etc. Rooms or locations: Window- priming and painting on interior side of window: Manufacturer: Color name and #:	1 EA 200 LF	\$ \$ \$ \$ \$ \$	0.00 521.98 2,211.48	\$ \$ \$ \$	0.00 600.27 2,543.21

NOTE: Our standard is low VOC for walls and ceilings. If client or designer prefers NO VOC for walls and or ceiling paint and primers, specify so during design.

Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition-tbd. Will use low VOC primer when able.

NOTE: Please note that when the client is doing the painting, they are responsible for caulking, filling nail holes, and repairing minor wall and ceiling dings. There will need to be a few rounds of touch-ups, due to the nature of construction, and that falls under the scope of the painter.

Subtotal - Category 24		\$ 6,656.06	\$ 7,654.47
25. Clean Up and Debris Removal			
Disposal and clean-up: -Remove all site prep, wipe down and broom sweep areaHaul all extra material off site. NOTE: This doesn't include professional cleaning. Deep clean available at additional cost to be handled on a change order at end of project.	1 EA	\$ 278.09	\$ 319.80
Street permit: -Minneapolis street use permit for dumpster or unit temp storage. NOTE: If dumpster can be placed on driveway or lawn this can cost can be saved.	1 MO	\$ 182.00	\$ 209.3
NOTE: If the dumpster is placed on the street, and the city calls a snow emergency or street of be an additional ~\$200 charge per move or violation via a change order. Sometimes it will ge sometimes it will just get fined. The charge is the same either way.	-		
10 Yard mini roll-off dumpster: -Smaller truck for smaller places2.5 ton maximum NOTE: for 30 days only. See line below for additional months.	1 EA	\$ 564.75	\$ 649.4
Subtotal - Category 25		\$ 1,024.83	\$ 1,178.50
Project Subtotal		\$ 36,215.57	\$ 41,595.4
26. Designer Oversight & Project Management		\$ 3,802.63	\$ 4,373.0
27. Overhead and Profit		\$ 5,975.57	\$ 6,871.90
Grand Total**		\$ 45,993.77	\$ 52,892.84
MN License # BC005657			
Important Notice			
**This is only a ballpark guesstimate. This does not represent actual p best guess based on Castle's past experiences. There are still many unl can affect pricing at this point.	•		

Check or Cash Discount Low	\$ 1,149.84	Check or Cash	\$ 1,322.32	\$ 44,843.93	\$ 51,570.52	2
		Discount High				
2.5%*		2.5%*				

^{*}Doesn't Apply to Bank Financing or loan process that requires Castle to receive payment directly from that entity after Castle has paid subcontractors and secured lien waivers. In these instances Castle essentially acts as the financier for the project and incurs borrowing costs. Exceptions include banks willing to follow Castle payment structure.

Custom Design Studio Locations



362 Snelling Ave S. St. Paul, MN 55105 P) 651-699-4164



5 W. Diamond Lake Rd Minneapolis, MN 55419 P) 612-789-8509



2600 Johnson St. NE Minneapolis, MN 55418 P) 612-789-8509



6480 Wayzata Blvd. Golden Valley, MN 55426 P) 763-333-0750

Need Help with Financing Options?



HTTPS://WWW.CASTLEBRI.COM/FINANCING-OPTIONS/