

BUDGET ANALYSIS

Client Information:

Front Door & Storm Door Replacement

Address:

City, State, Zip:

Phone: Email:

Project Description:

Remove & replace front entryway door & storm door with all new interior & exterior trim. Presumes no changes to the door size or location.

	Qty. Unit Imag	ge Low B	udget	High B	udget
1. Permits and Design					
Permit.	1 EA	\$	375.00	\$	412.:
<u>Design and Planning Process</u> - see Design and Planning Agreement for details.	1 EA	\$	500.00	\$	500.
abtotal - Category 1		\$	875.00	\$	912.
2. Site Prep and Demolition					
Site Prep Small to Medium Project: -Tools/equipment delivery and set up of job sitePlace yard sign and order dumpsterFloor protection to work areaPoly curtain walls and zipper doors to work area.	1 EA	\$	648.50	\$	713.
Demolition of work area: - Demo interior and exterior trim around front entry doorway. - Demo front entryway door & storm door.	1 EA	\$	336.00	\$	369.0
NOTE: Although care is taken to carefully complete demolition, screw pops, hairline cr occasionally arise in adjacent spaces. No costs are included in this estimate to patch dr walls in adjacent spaces, but the need could arise. We also use the most expensive and prep to the floor, walls, or trim. If it is a bad or old finish, there is a small chance that is existing finish. Any additional repairs will be an extra charge and dealt with via Chang	ywall or plaster or repaint sensitive tape when taping it may peel off some of the				
occasionally arise in adjacent spaces. No costs are included in this estimate to patch dr walls in adjacent spaces, but the need could arise. We also use the most expensive and prep to the floor, walls, or trim. If it is a bad or old finish, there is a small chance that i	ywall or plaster or repaint sensitive tape when taping it may peel off some of the	\$	984.50	\$	1,082.
occasionally arise in adjacent spaces. No costs are included in this estimate to patch dr walls in adjacent spaces, but the need could arise. We also use the most expensive and prep to the floor, walls, or trim. If it is a bad or old finish, there is a small chance that i existing finish. Any additional repairs will be an extra charge and dealt with via Chang	ywall or plaster or repaint sensitive tape when taping it may peel off some of the	\$	984.50	\$	1,082.
occasionally arise in adjacent spaces. No costs are included in this estimate to patch dr walls in adjacent spaces, but the need could arise. We also use the most expensive and prep to the floor, walls, or trim. If it is a bad or old finish, there is a small chance that i existing finish. Any additional repairs will be an extra charge and dealt with via Chang abtotal - Category 2	ywall or plaster or repaint sensitive tape when taping it may peel off some of the	\$	984.50	\$	1,082.
occasionally arise in adjacent spaces. No costs are included in this estimate to patch dr walls in adjacent spaces, but the need could arise. We also use the most expensive and prep to the floor, walls, or trim. If it is a bad or old finish, there is a small chance that is existing finish. Any additional repairs will be an extra charge and dealt with via Chang abtotal - Category 2 3. Landscaping and Fence	ywall or plaster or repaint sensitive tape when taping it may peel off some of the	\$	984.50	\$	1,082.
occasionally arise in adjacent spaces. No costs are included in this estimate to patch dr walls in adjacent spaces, but the need could arise. We also use the most expensive and prep to the floor, walls, or trim. If it is a bad or old finish, there is a small chance that is existing finish. Any additional repairs will be an extra charge and dealt with via Chang abtotal - Category 2 3. Landscaping and Fence NOTE: Any landscaping work to be done by Field Outdoor Spaces or Client.	ywall or plaster or repaint sensitive tape when taping it may peel off some of the		984.50		1,082.

Subtotal - Category 5		\$	-	\$	-
06. Framing					
Presumes that the existing framing of the front door opening is in a serviceable state. No framing work is included in this project. If it is found that the framing of the door opening is in need of repair, a change order will be incurred.	1 Note	\$	0.00	\$	0.00
Subtotal - Category 6		\$	0.00	\$	0.00
09. Roofing, Flashing, Gutters					
Subtotal - Category 9		\$		\$	-
10. Exterior Trim, Porches and Decks					
EXTERIOR TRIM:	0 EA	\$	_	\$	-
Trim- Hardie prefinished: Width: Standard Pre-Finished Color or primed:	20 LF	\$	183.15	\$	201.47
Profile:					
Texture:			105.15		
Subtotal - Category 10		\$	183.15	\$	201.47
11. Siding, Soffit, and Fascia	1.37	ф	0.00	ф	0.00
No siding work is included in this project.	1 Note	\$	0.00	\$	0.00
Subtotal - Category 11		\$	0.00	\$	0.00
12. Exterior Doors and Trim					
IRA tax rebate eligible exterior door product info: https://www.energystar.gov/about/federal_tax_credits/exterior_doors	0 NOTE	\$	-	\$	-
nttps://www.energystar.gov/about/rederai_tax_credits/exterior_doors Entry door:	1 EA	\$	1,645.00	\$	1,809.50
\$900 allowance	I EA	Φ	1,043.00	Ф	1,809.30
Manufacturer:					
Model:					
Type: Exterior color:					
Interior color:					
Glass:					
Grids (type, size, pattern, color): Interior weather strip color:					
Sill/threshold color:					
Bore (single or double): Exterior Brickmould profile/material/color/size: if comes with door, if not specify under section					
10 Full view storm door:	1 EA	\$	1,064.50	\$	1,170.95
\$600 allowance	1 2.1	Ψ	1,000	Ψ	1,170,50
Manufacturer:					
Model: Door Color:					
Hardware Color:					
Deadbolt lock and knob set:	1 EA	\$	333.00	\$	366.30
\$200 allowance					
Manufacturer:					
Model: Color:					
Subtotal - Category 12		\$	3,042.50	\$	3,346.75
18. Drywall					
Drywall or plaster patch around front entry door.	1 EA	\$	153.00	\$	168.30
Subtotal - Category 18		\$	153.00	\$	168.30
19. Tile and Stone					
Subtotal - Category 19		\$	-	\$	-
20. Millwork, Doors, Hardware					
Casing- classic 1X with a backband:	20 LF	\$	780.10	\$	858.11
Manufacturer:					
Model backband: Model 1x:					
Species:					
Size overall:					
Picture framed: Y or N					
Stool detail (thickness/extension) and apron detail (height, model #): or NA					
Location:		I		I	

ıbtotal - Category 20	\$	780.10	\$ 858.11	
1. Cabinetry, Countertops and Appliances				
abtotal - Category 21			0.00	\$ 0.00
2. Specialties				
btotal - Category 22			-	\$ -
3. Flooring				
btotal - Category 23			0.00	\$ 0.00
4. Painting and Decorating				
In house set up, prep, clean up- 1 room.	1 EA	\$	493.25	\$ 542.58
<u>Walls</u> - prime and paint so that drywall patch blends with the rest of the room: <u>Manufacturer</u> :	100 SF	\$	334.75	\$ 368.23
Color name and #: Sheen:				
Rooms:				
Molding (base, casing)- staining and sealing: Manufacturer:	20 LF	\$	517.70	\$ 569.47
Color name and #: Sheen: satin is standard				
Items: base, casing, crown, etc. Rooms or locations:				
Exterior door- finish: Manufacturer:	1 EA	\$	615.88	\$ 677.46
Color name and # door: Color name and # jamb:				
Sheen: satin is standard Locations:				
NOTE: includes both sides and jamb of unit.				
<u>Paint (wall) & stain (interior trim & door) match</u> by Castle. Take sample to store, get matched, and approved by client.	2 EA	\$	462.00	\$ 508.20
Presumes all exterior surfaces (storm door, exterior trim, etc.) are pre-finished from the supplier(s). No exterior paint/stain work included in this project.	1 Note	\$	0.00	\$ 0.00

NOTE: Our standard is low VOC for walls and ceilings. If client or designer prefers NO VOC for walls and or ceiling paint and primers, specify so during design.

Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.

NOTE: Please note that when the client is doing the painting, they are responsible for caulking, filling nail holes, and repairing minor wall and ceiling dings. There will need to be a few rounds of touch-ups, due to the nature of construction, and that falls under the scope of the painter.

tal - Category 24	\$	2,423.58	\$	2,665.9	
Clean Up and Debris Removal	d Debris Removal				
	0 EA	\$	-	\$	-
	0 EA	\$	-	\$	-
Disposal and clean-up:	1 EA	\$	336.00	\$	369.6
-Remove all site prep, wipe down and broom sweep area.					
-Haul all extra material off site.					
NOTE: This doesn't include professional cleaning. Deep clean available at additional	NOTE: This doesn't include professional cleaning. Deep clean available at additional cost to be				
handled on a change order at end of project.	handled on a change order at end of project.				
NOTE: If the dumpster is placed on the street, and the city calls a snow emergency be an additional ~\$200 charge per move or violation via a change order. Sometimes it will just get fined. The charge is the same either way.	٥,				
be an additional ~\$200 charge per move or violation via a change order. Sometimes it will just get fined. The charge is the same either way.	it will get moved, sometimes		242.55	Lo	
be an additional ~\$200 charge per move or violation via a change order. Sometimes it will just get fined. The charge is the same either way. Bagster:	٥,	\$	243.75	\$	268.
be an additional ~\$200 charge per move or violation via a change order. Sometimes it will just get fined. The charge is the same either way.	it will get moved, sometimes	\$	243.75	\$	268.
be an additional ~\$200 charge per move or violation via a change order. Sometimes it will just get fined. The charge is the same either way. Bagster:	it will get moved, sometimes	\$	243.75	\$	268.
be an additional ~\$200 charge per move or violation via a change order. Sometimes it will just get fined. The charge is the same either way. Bagster: Place Baster on driveway or boulevard accessible to street for pickup.	it will get moved, sometimes	\$	243.75		268.
be an additional ~\$200 charge per move or violation via a change order. Sometimes it will just get fined. The charge is the same either way. Bagster: Place Baster on driveway or boulevard accessible to street for pickup. Portable restroom: Aditional cost if needed.	it will get moved, sometimes 1 EA 0 MO	\$	243.75		268.
be an additional ~\$200 charge per move or violation via a change order. Sometimes it will just get fined. The charge is the same either way. Bagster: Place Baster on driveway or boulevard accessible to street for pickup. Portable restroom: Aditional cost if neededRegular.	it will get moved, sometimes 1 EA 0 MO	\$	243.75		268.

Project Subtotal							\$ 9,021.58	\$ 9,873.73
26. Designer Oversight & Project Management					\$ 1,037.48	\$ 1,141.23		
27. Overhead and Profit					\$ 1,488.56	\$ 1,637.42		
Grand Total**							\$ 11,547.62	\$ 12,702.38
MN License #	BC005657							
Important Notice								
**This is only a ballpark g	guesstimate. This	does not	represent actual p	rices	, only a			
best guess based on Castle's	past experiences.	There a	re still many unkn	owns	that can			
affect pricing at this point.								
Check or Cash Discount Low 2.5%*	\$	288.69	Check or Cash Discount High 2.5%*	\$	317.56		\$ 11,258.93	\$ 12,384.82

^{*}Doesn't Apply to Bank Financing or loan process that requires Castle to receive payment directly from that entity after Castle has paid subcontractors and secured lien waivers. In these instances Castle essentially acts as the financier for the project and incurs borrowing costs. Exceptions include banks willing to follow Castle payment structure.

Custom Design Showrooms



5 W. Diamond Lake Rd Minneapolis, MN 55419 P) 612-789-8509



2600 Johnson St. NE Minneapolis, MN 55418 P) 612-789-8509



362 Snelling Ave S. St. Paul, MN 55105 P) 651-699-4164

Showroom maps & hours can be found on our website at www.CASTLEBRI.com

Need Help with Financing Options?



HTTPS://WWW.CASTLEBRI.COM/FINANCING-OPTIONS/