

## **BUDGET ANALYSIS**

## **Client Information:**

Client Name Address Address Phone Email

## **Project Description:**

Add gabled awning with brackets over front door. No interior work included. Electrical by homeowner. Includes redoing all shakes in existing front gable and repainting front façade of home.

	Qty. Unit	Unit Image Low Budge		Low Budget		Low Budget		Low Budget		Low Budget		Low Budget		udget
01. Permits and Design														
<u>Permit.</u>	1 EA		\$	579.60	\$	637.5								
Design and Planning Process- PAID	1 EA		\$	700.00	\$	700.0								
Engineering allowance not included- City may require for permit issuing. Would be charged as change order if needed.	1 EA		\$	0.00	\$	0.0								
<b>Basic initial site plan.</b> <b>NOTE:</b> If after receiving this, set backs are in question/property lines very close to proposed addition, locating markers or a survey with a certified land surveyor may be needed.	1 EA		\$	157.50	\$	173.2								
ubtotal - Category 1			\$	1,437.10	\$	1,510.8								
2. Site Prep and Demolition														
<u>Site Prep Exterior/Handyman Project:</u> -Tools/equipment delivery and set up of job site. -Place yard sign and order dumpster. -Floor protection to work area.	1 EA		\$	201.68	\$	221.8								

Demolition of work area: - Demo gutter section on north side of home where new extension will be. - Demo fascia, rafter tails and soffit beadboard where new overhang will be.	1 EA	\$	1,377.60	\$ 1,515.3
<ul> <li>Remove and SAVE single corbel decorative bracket for homeowner.</li> <li>Remove and SAVE decorative plaque, mail box and door bell.</li> </ul>				
- Demo house numbers, light, and door casing/ head casing at exterior door. Exterior door to remain.				
- Demo siding at front gable peak				
- Remove and SAVE all siding as needed for new posts at new gable corbel brackets				
(vertical boards entire width of new overhang). - All windows and other items to remain.				
Scaffolding- set up and take down for exterior work or addition.	1 EA	\$	569.10	\$ 626.0
NOTE: Although care is taken to carefully complete demolition, screw pops, hairline cracks, and occasionally arise in adjacent spaces. No costs are included in this estimate to patch drywall or p walls in adjacent spaces, but the need could arise. We also use the most expensive and sensitive to prep to the floor, walls, or trim. If it is a bad or old finish, there is a small chance that it may pee existing finish. Any additional repairs will be an extra charge and dealt with via Change Order.	laster or repaint ape when taping			
ubtotal - Category 2		\$	2,148.38	\$ 2,363.2
3. Landscaping and Fence				
NOTE: Any landscaping work to be done by Field Outdoor Spaces or Client.				
No landscape work is included in this proposal, including fixing any landscape damage potential from working around landscaped areas.	1 NOTE	\$	0.00	\$ 0.0
ubtotal - Category 3		\$	0.00	\$ 0.0
4. Concrete and Foundation				
5. Masonry				
6. Framing				
- Add post (min 2x4) at 3 locations - one at each new gable corbel bracket, to foundation and/or existing door header. Posts for gable brackets to be screwed into for structural support.	1 EA	\$	3,188.28	\$ 3,507.1
- Frame new gable roof overhang - 4' deep - centered over existing exterior door. Open rafter design, new rafter tails to match existing on home.				
- Frame new paint grade mounting block for homeowner provided sconce.				
ubtotal - Category 6		\$	3,188.28	\$ 3,507.1
9. Roofing, Flashing, Gutters				
Install HOMEOWNER PROVIDED asphalt shingles on new roof overhang. Flash into	1 EA	\$	1,285.20	\$ 1,413.7
<u>existing roof as needed.</u> Manufacturer: Homeowner has 2 shingle bundles.				
Type: Asphalt assumed.				
Includes starter strip, ice and water, ridge cap, roof edge, etc. NOTE: tie in of new to old may be noticeable and not match exactly due to weather/fading, etc.				
Gutters- standard 5" k style	1 EA	\$	300.30	\$ 330.3
<b>Color: MATCH EXISTING - VERIFY ON SITE</b> Replace gutter section on north side with new longer piece to included extended soffit/overhang.				
New gutter piece on south side of new overhang. NO downspouts included - HOMEOWNER				
to install rain chain (HOMEOWNER PROVIDED) after Castle is complete - on south overhang extension.				
Excludes leaf gaurd.				
ubtotal - Category 9		\$	1,585.50	\$ 1,744.0
0. Exterior Trim, Porches and Decks		\$	-	\$ -
U. Exterior Trim, Porches and Decks <u>EXTERIOR TRIM:</u>	0 EA	φ		
EXTERIOR TRIM: Trim- paint grade at exterior door only:	0 EA 20 LF	\$ \$	186.48	\$ 205.1
EXTERIOR TRIM: <u>Trim- paint grade at exterior door only:</u> Width: Hardie 5.5" X 12' PRIMED TRIM			186.48	\$ 205.1
EXTERIOR TRIM: Trim- paint grade at exterior door only:			186.48	\$ 205.1

Style: TBD	\$ 1,111.95	\$ 1,223.1
Style: TBD Material: Paint grade or pine		
Allowance: \$230 per bracket		
ubtotal - Category 10	\$ 1,298.43	\$ 1,428.2
1. Siding, Soffit, and Fascia		
House wrap-1 layer Tyvek where siding replaced (front peak and area below peak). 200 SF	\$ 348.60	\$ 383.4
Furnish and & install ~8 new pieces of 9" wide groove to groove vertical redwood cedar plant       1 EA         siding. Custom milled T&G with V-groove- 1x9-10' #3 WP4 cedar siding to match. 3 week lead       1 EA         time.       Reinstall other vertical cedar planks removed for posting.         New cedar shakes will need to be installed at entire front gable of home, as we are not able to       1 EA         match existing and the existing ones will not salvage. Cedar 3/16" x 16" 5x are 4" to 14" wide       1 EA	\$ 4,140.62	\$ 4,554.6
<ul> <li>I bundles covers 25SF at 5" exposure.</li> <li>NOTE: Since siding is old painted wood, it may not remove nicely. If more new material is needed, a change order will be assessed.</li> </ul>		
Soffits- Plywood:1 EABeadboard - match existing as closely as possible - tongue and groove, paint grade. At new overhangs over front entry only. Vented or non-vented: non-vented Also includes frieze board with 1 3/4" beadmolding.1 EA	\$ 964.40	\$ 1,060.3
Subtotal - Category 11	\$ 5,453.63	\$ 5,998.9
12. Exterior Doors and Trim	-,	-,
3. Windows		
L4. Plumbing		
L5. HVAC		
<b>16. Electrical - BY HOMEOWNER</b> NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued.		
NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle		
functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued. NOTE: No wiring for security, doorbell, TV, speakers or phone is included in pricing. If any low voltage wires	\$ 0.00	\$ 0.0
NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued. NOTE: No wiring for security, doorbell, TV, speakers or phone is included in pricing. If any low voltage wires are found in a wall being opened up, additional costs to re-route them will occur.	\$ 0.00 0.00	0.0
NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued.         NOTE: No wiring for security, doorbell, TV, speakers or phone is included in pricing. If any low voltage wires are found in a wall being opened up, additional costs to re-route them will occur.         Electrical Permit. BY HOMEOWNER       1 NOTE         - Demo existing light at door & wiring. BY HOMEOWNER       1 NOTE         - Furnish and install new sconce light on existing switch. BY HOMEOWNER       1 NOTE         - Re-hook up door bell. BY HOMEOWNER       2 NOTE		
NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued.         NOTE: No wiring for security, doorbell, TV, speakers or phone is included in pricing. If any low voltage wires are found in a wall being opened up, additional costs to re-route them will occur.         Electrical Permit. BY HOMEOWNER       1 NOTE         - Demo existing light at door & wiring. BY HOMEOWNER       1 NOTE         - Furnish and install new sconce light on existing switch. BY HOMEOWNER       1 NOTE         - Re-hook up door bell. BY HOMEOWNER       1 NOTE         17. Insulation       10 or bell. BY HOMEOWNER		
NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued.         NOTE: No wiring for security, doorbell, TV, speakers or phone is included in pricing. If any low voltage wires are found in a wall being opened up, additional costs to re-route them will occur.         Electrical Permit. BY HOMEOWNER       1 NOTE         - Demo existing light at door & wiring. BY HOMEOWNER       1 NOTE         - Furnish and install new sconce light on existing switch. BY HOMEOWNER       1 NOTE		\$
NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued.         NOTE: No wiring for security, doorbell, TV, speakers or phone is included in pricing. If any low voltage wires are found in a wall being opened up, additional costs to re-route them will occur.       1 NOTE         Electrical Permit. BY HOMEOWNER       1 NOTE         - Demo existing light at door & wiring. BY HOMEOWNER       1 NOTE         - Re-hook up door bell. BY HOMEOWNER       1 NOTE         17. Insulation       1         18. Drywall       No drywall work included.       1 NOTE         NOTE: Work from exterior may cause screw pops/cracking to interior walls/plaster. If this occurs, we can patch/paint and additional charges would be assessed via change order if needed.       1 NOTE	\$ 0.00	\$ 0.0
NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued.         NOTE: No wiring for security, doorbell, TV, speakers or phone is included in pricing. If any low voltage wires are found in a wall being opened up, additional costs to re-route them will occur.         Electrical Permit. BY HOMEOWNER       1 NOTE         - Demo existing light at door & wiring. BY HOMEOWNER       1 NOTE         - Furnish and install new sconce light on existing switch. BY HOMEOWNER       1 NOTE <b>17. Insulation</b> 18. Drywall         No drywall work included.       1 NOTE         NOTE: Work from exterior may cause screw pops/cracking to interior walls/plaster. If this       1 NOTE	\$  0.00	\$ 0.0
NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued.         NOTE: No wiring for security, doorbell, TV, speakers or phone is included in pricing. If any low voltage wires are found in a wall being opened up, additional costs to re-route them will occur.       I NOTE         Electrical Permit. BY HOMEOWNER       1 NOTE         - Furnish and install new sconce light on existing switch. BY HOMEOWNER       1 NOTE         - Re-hook up door bell. BY HOMEOWNER       1 NOTE         NOTE: Work included.       1 NOTE         * Re-hook up door bell. BY HOMEOWNER       1 NOTE         * Re-hook up door bell. BY HOMEOWNER       1 NOTE         * Re-hook up door bell. BY HOMEOWNER       1 NOTE         * Re-hook up door bell. BY HOMEOWNER       1 NOTE         * Re-hook up door bell. BY HOMEOWNER       1 NOTE         * Re-hook up door bell. BY HOMEOWNER       1 NOTE         * Storywall       1 NOTE         * Ortywall work included.       1 NOTE         * Orty was an exterior may cause screw pops/cracking to interior walls/plaster. If this occurs, we can patch/paint and additional charges would be	\$  0.00	\$ 0.0
NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued.         NOTE: No wiring for security, doorbell, TV, speakers or phone is included in pricing. If any low voltage wires are found in a wall being opened up, additional costs to re-route them will occur.       I NOTE         Electrical Permit. BY HOMEOWNER       1 NOTE         • Demo existing light at door & wiring. BY HOMEOWNER       1 NOTE         • Re-hook up door bell. BY HOMEOWNER       1 NOTE         NOTE: Work from exterior may cause screw pops/cracking to interior walls/plaster. If this occurs, we can patch/paint and additional charges would be assessed via change order if needed.       1 NOTE         Subtotal - Category 18       19. Tile and Stone       1         Q. Millwork, Doors, Hardware       2       1	\$  0.00	\$ 0.0
NOTE: Entire home must meet code requirements for smoke and CO detectors. All detectors need to be functional and placed per code. Code requires each floor to have one smoke detector. In addition, any bedroom needs a smoke detector. There must also be a carbon monoxide detector within 10 feet of each bedroom. If the rest of the home does not meet the above code, Client will be responsible to update it or if Client prefers, Castle will perform updates and a change order will be issued.         NOTE: No wiring for security, doorbell, TV, speakers or phone is included in pricing. If any low voltage wires are found in a wall being opened up, additional costs to re-route them will occur.       1 NOTE         Electrical Permit. BY HOMEOWNER       1 NOTE         - Demo existing light at door & wiring. BY HOMEOWNER       1 NOTE         - Re-hook up door bell. BY HOMEOWNER       1 NOTE         NOTE: Work included.       1 NOTE         17. Insulation       1 NOTE         18. Drywall       1 NOTE         NOTE: Work included.       1 NOTE         19. Work included.       1 NOTE         10. WORE: Work included.       1 NOTE         11. NOTE       1 NOTE         12. Work from exterior may cause screw pops/cracking to interior walls/plaster. If this occurs, we can patch/paint and additional charges would be assessed via change order if needed.         Subtotal - Category 18       18	\$  0.00	\$ 0.0

23. Flooring		\$	321.74	\$	353.9
24. Painting and Decorating					
	1 EA	\$	2,312.66	\$	2,543.9
- Prime and enamel new exterior door casings.					
- Prime and enamel vertical wood siding and cedar shake siding as needed from removal and reinstall. Price includes painting all siding and shakes at front of home where gable overhang is					
installed (approx 14' wide x 13' high).					
- Prime and enamel (3) new gable brackets.					
- Prime and enamel new sconce mounting block.					
- Prime and enamel new fascia. New and then one stretch of facia that goes back on the north					
side of the house- max 40 LF. - Prime & enamel bead board soffits to match existing.					
HOMEOWNERS TO PROVIDE PAINT COLORS, SHEEN AND BRAND USED;					
PAINTER TO PROVIDE PAINT.					
NOTE: Our standard is low VOC for walls and ceilings. If client or designer prefers NO VOC for walls ceiling paint and primers, specify so during design.		<u>.</u>			
Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existi stain/wood condition- tbd. Will use low VOC primer when able.	ing				
- -					
NOTE: Please note that when the client is doing the painting, they are responsible for caulking, fillin,	ng nail				
holes, and repairing minor wall and ceiling dings. There will need to be a few rounds of touch-ups, du	ue to the				
nature of construction, and that falls under the scope of the painter.					
ubtotal - Category 24		\$	2,312.66	\$	2,543
5. Clean Up and Debris Removal					
	1 EA	\$	197.17	\$	216.
-Remove all site prep, wipe down and broom sweep area.					
-Haul all extra material off site. <b>NOTE:</b> This doesn't include professional cleaning. Deep clean available at additional cost to be					
handled on a change order at end of project.					
	1 MO	\$	136.50	\$	150.
-Minneapolis street use permit for dumpster or unit temp storage.					
NOTE: If dumpster can be placed on driveway or lawn this can cost can be saved.					
NOTE: If the dumpster is placed on the street, and the city calls a snow emergency or street cleaning,					
be an additional ~\$200 charge per move or violation via a change order. Sometimes it will get moved, it will just get fined. The charge is the same either way.	sometimes				
	1 EA	\$	328.93	\$	361
-Smaller truck for smaller places.					
-Smaller truck for smaller places. -2.5 ton maximum.					
-Smaller truck for smaller places. -2.5 ton maximum. NOTE: For 30 days only. See line below for additional months.	1 MO	¢	240.45	¢	264
-Smaller truck for smaller places. -2.5 ton maximum. NOTE: For 30 days only. See line below for additional months. Portable restroom:	1 MO	\$	240.45	\$	264.
-Smaller truck for smaller places. -2.5 ton maximum. NOTE: For 30 days only. See line below for additional months.	1 MO	\$	240.45	\$	264
<ul> <li>-Smaller truck for smaller places.</li> <li>-2.5 ton maximum.</li> <li>NOTE: For 30 days only. See line below for additional months.</li> <li>Portable restroom: <ul> <li>-Regular.</li> <li>NOTE: This cost can be saved if Client is ok with making a bathroom in the house available to Castle and our trade partners.</li> </ul> </li> </ul>	1 MO	\$	240.45	\$	264
-Smaller truck for smaller places. -2.5 ton maximum. NOTE: For 30 days only. See line below for additional months. Portable restroom: -Regular. NOTE: This cost can be saved if Client is ok with making a bathroom in the house available to Castle and our trade partners. ubtotal - Category 25	1 MO	\$	903.05	\$	993
-Smaller truck for smaller places. -2.5 ton maximum. NOTE: For 30 days only. See line below for additional months. Portable restroom: -Regular. NOTE: This cost can be saved if Client is ok with making a bathroom in the house available to Castle and our trade partners. ubtotal - Category 25 roject Subtotal	1 MO	\$ \$	903.05 18,648.77	\$ \$	993 20,443
-Smaller truck for smaller places. -2.5 ton maximum. NOTE: For 30 days only. See line below for additional months. Portable restroom: -Regular. NOTE: This cost can be saved if Client is ok with making a bathroom in the house available to Castle and our trade partners. Subtotal - Category 25 Project Subtotal 6. Designer Oversight & Project Management	1 MO	\$ \$ \$	<b>903.05</b> <b>18,648.77</b> 2,144.61	\$ \$ \$	<b>993</b> <b>20,443</b> 2,359
-Smaller truck for smaller places. -2.5 ton maximum. NOTE: For 30 days only. See line below for additional months. Portable restroom: -Regular. NOTE: This cost can be saved if Client is ok with making a bathroom in the house available to Castle and our trade partners. Subtotal - Category 25 Project Subtotal 6. Designer Oversight & Project Management	1 MO	\$ \$	903.05 18,648.77	\$ \$	<b>993</b> . <b>20,443</b> . 2,359.
<ul> <li>-Smaller truck for smaller places.</li> <li>-2.5 ton maximum.</li> <li>NOTE: For 30 days only. See line below for additional months.</li> <li>Portable restroom: <ul> <li>-Regular.</li> <li>NOTE: This cost can be saved if Client is ok with making a bathroom in the house available to</li> </ul> </li> </ul>	1 MO	\$ \$ \$	<b>903.05</b> <b>18,648.77</b> 2,144.61	<b>\$</b> <b>\$</b> \$	264. 993. 20,443. 2,359. 3,384. 26,257.
-Smaller truck for smaller places. -2.5 ton maximum. NOTE: For 30 days only. See line below for additional months. Portable restroom: -Regular. NOTE: This cost can be saved if Client is ok with making a bathroom in the house available to Castle and our trade partners. ubtotal - Category 25 roject Subtotal 6. Designer Oversight & Project Management 7. Overhead and Profit	1 MO	<b>\$</b> <b>\$</b> \$	<b>903.05</b> <b>18,648.77</b> 2,144.61 3,077.05	<b>\$</b> <b>\$</b> \$	<b>993</b> <b>20,443</b> 2,359 3,384

	**Important Notice**						
**This is only a ballpark guesstimate. This does not represent actual prices, only a best guess based on Castle's past experiences. There are still many unknowns that can affect pricing at this point.							
Check or Cash Discount Low 2.5%*		Check or Cash Discount High 2.5%*	\$	656.44		\$ 23,273.67	\$ 25,601.04

\*Doesn't Apply to Bank Financing or loan process that requires Castle to receive payment directly from that entity after Castle has paid subcontractors and secured lien waivers. In these instances Castle essentially acts as the financier for the project and incurs borrowing costs. Exceptions include banks willing to follow Castle payment structure.

## **Custom Design Showrooms**



5 W. Diamond Lake Rd Minneapolis, MN 55419 P) 612-789-8509



2600 Johnson St. NE Minneapolis, MN 55418 P) 612-789-8509



362 Snelling Ave S. St. Paul, MN 55105 P) 651-699-4164

Showroom maps & hours can be found on our website at www.CASTLEBRI.com