**One Story Exterior Remodel** 

Address:

City, State, Zip:

Phone: Email:



## **BUDGET ANALYSIS**

Project Description: Date: 6/8/2022

Complete exterior renovation of one story rambler including siding replacement, new full frame casement windows, aluminum soffit and fascia, gutters with leaf guards, painting of the brick, and a portico addition and front entry.

	Qty. Unit	Low I	Budget	High	Budget
01. Permits and Design					
Permit	1 EA	\$	2,990.00	\$	3,438.50
Design and Planning Process See Design and Planning Agreement for Details.	1 EA	\$	6,800.00	\$	6,800.00
Subtotal - Category 1		\$	9,790.00	\$	10,238.50
02. Site Prep and Demolition					
Site Prep Large Project or Addition (Includes floor protection, poly curtain walls, and delivery of tools/equipment and set up of job site). Place yard sign and order dumpster. Protect floors through home to work area. Install poly curtain walls and zipper doors to work area.	1 EA	\$	1,868.40	\$	2,148.66
•Demo siding from home and dispose of in dumpster (by siding TP).	1 EA	\$	1,478.40	\$	1,700.16
•Remove gutters and downspouts and recycle aluminum (by siding TP).		ľ	,	,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
•Remove soffits and dispose of wood (by siding TP).					
•Remove 14 casement windows and associated trim (by Castle).					
•(Existing concrete stoop to remain in place.)					
•(Does NOT include mold, lead, and/or asbestos abatement. If abatement measures are found to					
be necessary, additional costs will be included via a change order).	1 137.		0.00		0.00
NOTE: Although care is taken to carefully remove materials from wall and floor surfaces, screw pops, hairline cracks, and other issues can occasionally arise in adjacent spaces. No	1 Note	\$	0.00	\$	0.00
costs are included in this estimate to patch drywall or plaster or repaint walls in adjacent					
spaces but the need could arise and can be handled with a Change Order. We also use the					
most expensive and sensitive tape when taping prep to the floor, walls, or trim. If it is a bad					
or old finish, there is a small chance that it may peel some of the existing finish off. Any					
additional repairs will be an additional charge and dealt with via Change Order.					
Subtotal - Category 2		\$	3,346.80	\$	3,848.82
03. Landscaping and Fence - By Field Outdoor Spaces or homeowner					
Presumes no landscaping work included in this project.	1 Note	\$	0.00	\$	0.00
Subtotal - Category 3		\$	0.00	\$	0.00
04. Concrete and Foundation Pier Footings - 12" X42" with 18" bell	2 EA	\$	856.20	\$	984.63
Flat concrete work. 4" slab. Patio / Driveway / Sidewalk	80 SF	\$	2,600.00	\$	2,990.00
		0	2.456.20	Φ.	2.074.62
Subtotal - Category 4 05. Masonry		\$	3,456.20	3	3,974.63
Tuck-pointing of brick work.	1 EA	\$	2,860.00	\$	3,289.00
Subtotal - Category 5		\$	2,860.00	\$	3,289.00
06. Framing					
Install portico support framing.	4 EA	\$	1,259.20	\$	1,448.08
Frame portico entry roof. Includes 1/2" OSB, "H" clips @ 24" O.C stick framed (materials and labor)	140 SF	\$	4,340.28	\$	4,991.32
Furnish and install new 1 3/4" X 11 7/8" LVL ridge beam (materials and labor)	12 LF	\$	1,133.28	\$	1,303.27
Subtotal - Category 6		\$	6,732.76	\$	7,742.67

		_			
<b>09. Roofing, Flashing, Gutters</b> Roofing - Furnish and install asphalt shingles. Install only. (for additions and new roofs)	140 SF	\$	1,092.00	\$	1,255.80
Shingle manufacturer:	140 51	Ф	1,092.00	Ф	1,233.60
Shingle type:					
Shinigle type.					
	204 7 7		0.100.40	_	0.240.56
Option: Furnish and install leaf free gutters and 3x4 downspouts.	284 LF	\$	8,122.40	\$	9,340.76
Color:					
Subtotal - Category 9		\$	9,214.40	\$	10,596.56
10. Exterior Trim, Porches and Decks				Φ.	
Subtotal - Category 10		\$	-	\$	-
11. Siding, Soffit, and Fascia  Demo siding in affected areas	1760 SF	\$	6,726.72	\$	7,735.73
	1760 SF				
Furnish and install 1 layer Tyvek house wrap		\$	2,860.00	\$	3,289.00
Siding - Hardie fiber cement board siding - ?" lap. Includes 5/4 X ? Corner pieces, and window	1760 SF	\$	28,828.80	\$	33,153.12
and door trim.					
Manufacturer:					
Color:					
Trim width:					
Lap size:					
Portico Soffits - Plywood	140 SF	\$	4,550.00	\$	5,232.50
smooth or bead board					
Soffits and Fascia - Aluminum	248 LF	\$	6,770.40	\$	7,785.96
Color:		l'	-,	`	.,
		_			
Subtotal - Category 11		\$	49,735.92	\$	57,196.31
12. Exterior Doors and Trim Subtotal - Category 12		\$	0.00	\$	0.00
		- 3	0.00	3	0.00
13. Windows  Furnish and install new clad/wood full frame window;	14 EA	\$	22 045 40	\$	26,502.21
Window allowance \$950.00/ea.	14 EA	Ф	23,045.40	Ф	20,302.21
Manufacturer:					
Line:					
Operation type, size, jamb, tempering, egress notes: see plan/schedule					
Exterior material /color:					
Interior material /color:					
Glass: clear Low E2 w/ Argon is standard- modify if something else desired					
Grids (type, size, pattern, color):					
Interior weather Strip color: ???					
Hardware type/color:					
WOCD: Y or N (and specify color, if diff. from hardware)					
Screen surround material/color:					
Screen color:					
Exterior Brickmould profile/material/color/size: if comes with window, if not specify under					
	14.50		A	_	
Window install material (flashing, caulk, shims, etc.)	14 EA	\$	910.00	\$	1,046.50
Exterior window trim (brickmould) to be integral to new window unit.	14 EA	\$	2,275.00	\$	2,616.25
Manufacturer:			,		ĺ
Color:					
Material:					
Size:					
Style:					
Subtotal - Category 13		\$	26,230.40	\$	30,164.96
14. Plumbing					
Subtotal - Category 14		\$	-	\$	-
15. HVAC					
Subtotal - Category 15		\$	-	\$	-
16. Electrical		_			
TO. ERCURCAI					
Run wiring for exterior light fixtures and outlets.	1 EA	\$	1,560.00	\$	1,794.00
	1 EA 1 EA	\$ \$	1,560.00 240.50		1,794.00 276.58

Finish:   NOTE: For all home owner provided fixtures, there may be additional install costs for more complicated fixtures. ALL light fixtures must be specified prior to contract signing and be UL listed to pass inspection. All material issues related to materials supplied by once are the responsibility of the owner to resolve. Extra trade partner trip charges may apply for return visits if material issues can not be resolved in timely manner.	1,704.30	\$	1,482.00	\$	3 EA	Front portico & back door lights: CBR furnish and elec install light fixture;  Fixture allowance \$250.00/ea.  Manufacturer:  Model #:
Subtotal - Category 16  17. Insulation  Subtotal - Category 17  SSUBTOTAL - Category 17  SSUBTOTAL - Category 18  SSUBTOTAL - Category 18  SSUBTOTAL - Category 18  SSUBTOTAL - Category 19  20. Millwork, Doors, Hardware  Moderate window easing - NOTE: Assumes 2 1/4"casing and "picture framed" windows Species: Species: Species: Species: Species: Species: Species: Species: Species: Subtotal - Category 20  21. Cabinetry, Countertops and Appliances  Subtotal - Category 21  22. Specialities Furnish and install new house numbers and mailbox, Allowance for letters \$50; Allowance for letter	0.00	\$	0.00	\$	1 Note	NOTE: For all home owner provided fixtures, there may be additional install costs for more complicated fixtures. ALL light fixtures must be specified prior to contract signing and be UL listed to pass inspection. All material issues related to materials supplied by owner are the responsibility of the owner to resolve. Extra trade partner trip charges may apply for
Subtotal - Category 17  18. Drywall  Subrotal - Category 18  19. Itle and Stone  Subtotal - Category 19  20. Millwork, Doors, Hardware Moderate window casing - NOTE: Assumes 2 1/4"casing and "picture framed" windows 280 LF \$ 2,979.76 \$ 5 \$ 5.0 \$ 5.0 \$ 5 \$ 5.0 \$ 5 \$ 5 \$ 5 \$ 5 \$ 5 \$ 5 \$ 5 \$ 5 \$ 5 \$	3,774.88	\$	3,282.50	\$		
IB. Driwall Subtotal - Category 18 5. 1- S 1- Tile and Stone Subtotal - Category 19 5. 1- S Subtotal - Category 19 7. 1- Subtotal - Category 19 8 S Subtotal - Category 19 8 S Subcotal - Category 19 8 S Species: Size: Brandprofile #: Picture framed** Y or N Stool detail (thickness/extension) and apron detail (height, profile #):  Subtotal - Category 20 8. 2.979.76 S 21. Cabinetry, Countertops and Appliances Subtotal - Category 21 8 S Subtotal - Category 22 8 S Subtotal - Category 23 8 S S Subtotal - Category 23 8 S S Subtotal - Category 23 8 S S Subtotal - Category 25 S S Subtotal - Category 25 S S S S S S S S S S S S S S S S S S S						
Sabbotal - Category 18 D. Hie and Stone Subtotal - Category 19 S. D. Millwork, Doors, Hardware Moderate window easing - NOTE: Assumes 2 1/4"casing and "picture framed" windows 280 LF Species: Size: Brand/profile #: "Picture framed": Yor N Stool detail (thickness/extension) and apron detail (height, profile #):  Subtotal - Category 20 S. 2,979.76 Subtotal - Category 21 S. Detail - Category 21 S. Subtotal - Category 21 S. Specialties Furnish and install new house numbers and mailbox. Allowance for letters \$50; Allowance for Subtotal - Category 21 S. Subtotal - Category 22 S. Specialties Furnish and install new house numbers and mailbox. Allowance for letters \$50; Allowance for Subtotal - Category 21 S. Jenoring Subtotal - Category 23 S. Flooring In house set up, prep, clean up In house set up, prep, clean up Priming and painting of base molding and/or easing. NOTE: Our standard is low VOC for. Subtotal - Category 23 S. Plooring In house set up, prep, clean up Priming and painting of base molding and/or easing. NOTE: Our standard is low VOC for. Subtotal - Category 23 S. Flooring S. Sheen: (satin is standard) Staining and finishing on interior side of window, one side. Manufacturer: Color name and #: Sheen: (satin is standard) Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC primer due to existing stain/wood. condition: bd. Will use low VOC primer when able. Manufacturer: Color name and #: Sheen: (satin is standard) Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC finer continue to existing stain/wood. condition: bd. Will use low VOC primer when able. Manufacturer: Color name and #: Sheen: (satin is standard)	-	\$	-	\$		
19. Tite and Stone		6		o o		
Subtotal - Category 19  20. Millwork, Doors, Hardware  Moderate window casing - NOTE: Assumes 2 1/4"casing and "picture framed" windows Species: Size: Brand/profile #: "Picture framed": Y or N Stool detail (thickness/extension) and apron detail (height, profile #):  Subtotal - Category 20  21. Cabinetry, Countertops and Appliances  Subtotal - Category 21  22. Specialties  Furnish and install new house numbers and mailbox. Allowance for letters \$50; Allowance for 1 EA 5 379.80 \$ Subtotal - Category 22  23. Flooring Subtotal - Category 23  24. Painting and Decorating  In house set up, prep, clean up Priming and painting of base molding and/or casing. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood. condition: thd. Will use low VOC primer when able. Manufacturer: Color name and #: Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. Manufacturer: Color name and #: Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. Manufacturer: Color name and #: Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. Manufacturer: Color name and #: Sheen: (satin is standard)	-	3	-	13		
20. Millwork, Doors, Hardware Moderate window asing - NOTE: Assumes 2 1/4"casing and "picture framed" windows Species: Size: Brand/profile #: "Picture framed": Yor N Stool detail (thickness/extension) and apron detail (height, profile #):  Subtotal - Category 20  21. Cabinetry, Countertops and Appliances  Subtotal - Category 21  22. Specialties  Furnish and install new house numbers and mailbox. Allowance for letters \$50; Allowance for 1 EA \$ 379.80 \$ Mailbox \$100.  Subtotal - Category 22  23. Flooring  Subtotal - Category 23  24. Painting and Decorating  In house set up, prep, clean up  Priming and painting of base molding and/or casing. NOTE: Our standard is low VOC for 280 LF \$ 2,158.80 \$ woodwork, although may not be able to use low VOC primer due to existing stain/wood condition-thd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC frimer due to existing stain/wood. condition- thd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)	-	\$	- 1	\$		
Species: Size: Brand/profile #:  "Picture framed": Y or N Stool detail (thickness/extension) and apron detail (height, profile #):  Subtotal - Category 20  21. Cabinetry, Countertops and Appliances Subtotal - Category 21  22. Specialties  Furnish and install new house numbers and mailbox. Allowance for letters \$50; Allowance for Mailbox \$100.  Subtotal - Category 22  23. Flooring Subtotal - Category 22  24. Painting and Decorating  In house set up, prep, clean up  Priming and painting of base molding and/or casing. NOTE: Our standard is low VOC for voodwork, although may not be able to use low VOC primer due to existing stain/wood. condition: thd. Will use low VOC primer when able.  Manufacturer:  Color name and #: Sheen: (sattin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC  for woodwork, although may not be able to use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (sattin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC  for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition: bd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (sattin is standard)						
21. Cabinetry, Countertops and Appliances  Subtotal - Category 21  22. Specialties  Furnish and install new house numbers and mailbox. Allowance for letters \$50; Allowance for 1 EA  \$ 379.80 \$  Subtotal - Category 22  \$ \$ 379.80 \$  Subtotal - Category 23  \$ \$ - \$  24. Painting and Decorating  In house set up, prep, clean up  Priming and painting of base molding and/or casing. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- thd. Will use low VOC primer when able.  Manufacturer:  Color name and #:  Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC  for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- thd. Will use low VOC primer when able.  Manufacturer:  Color name and #:  Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC  for woodwork, although may not be able to use low VOC primer due to existing stain/wood.  condition- thd. Will use low VOC primer when able.  Manufacturer:  Color name and #:  Sheen: (satin is standard)	3,426.72	\$	2,979.76	\$	280 LF	Species: Size: Brand/profile #: "Picture framed": Y or N
21. Cabinetry, Countertops and Appliances  Subtotal - Category 21  22. Specialties  Furnish and install new house numbers and mailbox. Allowance for letters \$50; Allowance for 1 EA  S 379.80 \$  Subtotal - Category 22  S 379.80 \$  Subtotal - Category 23  S - \$  24. Painting and Decorating  In house set up, prep, clean up  Priming and painting of base molding and/or casing. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- thd. Will use low VOC primer when able.  Manufacturer:  Color name and #:  Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC  for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- thd. Will use low VOC primer when able.  Manufacturer:  Color name and #:  Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC  for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- thd. Will use low VOC primer due to existing stain/wood condition- thd. Will use low VOC primer due to existing stain/wood condition- thd. Will use low VOC primer due to existing stain/wood condition- thd. Will use low VOC primer due to existing stain/wood condition- thd. Will use low VOC primer when able.  Manufacturer:  Color name and #:  Sheen: (satin is standard)	3,426.72	\$	2,979.76	\$		Subtotal - Category 20
Subtotal - Category 21  22. Specialties  Furnish and install new house numbers and mailbox. Allowance for letters \$50; Allowance	-, -:		,			
22. Specialties  Furnish and install new house numbers and mailbox. Allowance for letters \$50; Allowan		S	_	s		
Mailbox \$100.  Subtotal - Category 22  23. Flooring Subtotal - Category 23  24. Painting and Decorating In house set up, prep, clean up In house set up, prep,		Ψ				
23. Flooring Subtotal - Category 23 24. Painting and Decorating In house set up, prep, clean up Priming and painting of base molding and/or casing. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able. Manufacturer: Color name and #: Sheen: (satin is standard) Finishing of an EXTERIOR door both sides. Includes the jamb of the unit. NOTE: Our standard is low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able. Manufacturer: Color name and #: Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able. Manufacturer: Color name and #: Sheen: (satin is standard)	436.77	\$	379.80	\$	1 EA	
Subtotal - Category 23  24. Painting and Decorating  In house set up, prep, clean up  Priming and painting of base molding and/or casing. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer:  Color name and #:  Sheen: (satin is standard)  Finishing of an EXTERIOR door both sides. Includes the jamb of the unit. NOTE: Our standard is low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer:  Color name and #:  Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC the standard is low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer:  Color name and #:  Sheen: (satin is standard)	436.77	\$	379.80	\$		Subtotal - Category 22
In house set up, prep, clean up						
In house set up, prep, clean up  Priming and painting of base molding and/or casing. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition-tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)  Finishing of an EXTERIOR door both sides. Includes the jamb of the unit. NOTE: Our standard is low VOC primer due to existing stain/wood condition-tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition-tbd. Will use low VOC primer due to existing stain/wood condition-tbd. Will use low VOC primer due to existing stain/wood condition-tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)	-	\$	-	\$		
Priming and painting of base molding and/or casing. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)  Finishing of an EXTERIOR door both sides. Includes the jamb of the unit. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)	462.42	\$	402.10	¢	1 FA	
woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)  Finishing of an EXTERIOR door both sides. Includes the jamb of the unit. NOTE: Our 2 EA \$ 876.40 \$ standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC 14 EA \$ 5,306.00 \$ for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)		l '		1		
standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)  Staining and finishing on interior side of window, one side. NOTE: Our standard is low VOC 14 EA \$ 5,306.00 \$ for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)	2,482.62	\$	2,138.80	\$	280 LF	woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #:
for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #: Sheen: (satin is standard)	1,007.86	\$	876.40	\$	2 EA	standard is low VOC for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer:  Color name and #:
Castle paint or stain match	6,101.90	\$	5,306.00	\$	14 EA	for woodwork, although may not be able to use low VOC primer due to existing stain/wood condition- tbd. Will use low VOC primer when able.  Manufacturer: Color name and #:
	212.52	s	184.80	S	1 EA	Castle paint or stain match
Exterior Painting - Painting of portico plywood soffits & columns  1 EA  \$ 1,300.00 \$	1,495.00	1				-

Exterior Painting - Painting of brick	420 SF	\$ 1,092.00	\$ 1,255.80
Presumes all new Hardie siding, aluminum soffits, fascia, & exterior trim is pre-finished and therefor does not need to be painted. No additional exterior painting included in this project.	1 Note	\$ 0.00	\$ 0.00
NOTE: Please note that when the homeowner is doing the painting, they are responsible for caulking, filling nail holes, and repairing minor wall and ceiling dings. There will need to be a few rounds of touch-ups, due to the nature of construction, and that falls under the scope of the painter.	1 Note	\$ 0.00	\$ 0.00
total - Category 24		\$ 11,320.10	\$ 13,018.12
Clean Up and Debris Removal			
Disposal and clean-up - remove all site prep, wipe down and broom sweep area. Haul all extra material off site.	1 EA	\$ 739.20	\$ 850.08
Minneapolis daily street use permit for dumpster - Charged per 30 days. If dumpster can be placed on driveway or lawn this can cost can be saved.  NOTE: If the dumpster is required to be moved for plowing or street cleaning, there will be additional charges for moving it and replacing it after the street work is complete.	2 MO	\$ 160.00	\$ 160.00
ADD number of days, dumpster is estimated to be needed over 30 days	30 DAYS	\$ 210.00	\$ 210.00
<b>DUMPSTER NOTE:</b> If the dumpster is placed on the street, and the city calls a snow emergency or street cleaning, there will be an additional \$200 charge per move or violation via a change order. Sometimes it will get moved, sometimes it will just get fined. The charge is the same either way.	0 EA	\$ 0.00	\$ 0.00
20 Yard roll-off dumpster - 10 ton maximum <b>NOTE:</b> for 30 days only. Use line above for estimated days over 30 days	2 EA	\$ 871.00	\$ 1,001.6
Regular portable restroom (one month)  NOTE: This cost can be saved if home owner is ok with making a bathroom in the house available to Castle and it's trade partners	2 EA	\$ 442.00	\$ 508.30
otal - Category 25		\$ 2,422.20	\$ 2,730.0
ect Subtotal		\$ 131,861.84	\$ 150,437.9
Designer Oversight & Project Management		\$ 14,405.91	\$ 16,566.7
Overhead and Profit		\$ 20,669.34	\$ 23,769.7
and Total**		\$ 166,937.09	\$ 191,977.6
MN License # BC005657  **Important Notice**  **This is only a ballpark guesstimate. This does not represent actual probest guess based on Castle's past experiences. There are still many unknown affect pricing at this point.	, ,		
neck or Cash Discount Low 2.5%*  4,173.43 Check or Cash Discount High 2.5%*	\$ 4,799.44	\$ 162,763.66	\$ 187,178.2

<sup>\*</sup>Doesn't Apply to Bank Financing or loan process that requires Castle to receive payment directly from that entity after Castle has paid subcontractors and secured lien waivers. In these instances Castle essentially acts as

## **Custom Design Showrooms**

Showroom maps & hours can be found on our website at www.CASTLEBRI.com



W. Diamond Lake Rd Minneapolis, MN 55419 P) 612-789-8509



2600 Johnson St. NE Minneapolis, MN 55418 P) 612-789-8509



362 Snelling Ave S. St. Paul, MN 55105 P) 651-699-4164



4020 Minnehaha Ave Minneapolis, MN 55406 P) P) 612-789-8509



## Need Help with Financing Options?









https://www.castlebri.com/financing-options/

## **Castle Offers Financing**



Find out if you qualify

Call or email Tambra Heine, Financial Controller at 612.877.8374 or Tambra@castlebri.com to schedule your 10 minute no obligation consultation.